GOVERNMENT OF ANDHRA PRADESH ABSTRACT

Public Servants – Roads & Buildings Department – Charges issued against Sri T.Abbanna, the then Executive Engineer (R&B), Markapur (now Executive Engineer (R&B), Kakinada) for failure to monitor/supervise ROB at Rayavaram (V) of Podili-Markapur Road, Prakasam District – Penalty of stoppage of 4(Four) increments without cumulative effect - Orders – Issued.

TRANSPORT, ROADS & BUILDINS (VIG.I) DEPARTMENT

G.O.Rt.No. 1437

Dated.27-12-2012.

Read the following:-

- 1) Memo.No.284/VC(6)/2010-2, dt.07.12.2010 of the Engineer-in-Chief (R&B), Admn., & N.H., A.P., Hyderabad.
- 2) From Sri T.AbbannaA. Venugoapal, Executive Engineer (R&B) Division, Kakinada representation dated 12.01.2011.
- 3) From the G.A.(V&E) Department Vigilance Report No.8 (437)/V&E/E2/2010), dt. 24.01.2011.
- 4) From the Engineer-in-Chief (R&B), Admn., & N.H., A.P., Hyderabad Lr. No. 284/VC(6)/2010, dt. 24.08.2011 and 15.10.2012.

ORDER:

Charges were issued, vide reference first read above, against Sri T.Abbanna, the then Executive Engineer (R&B), Markapur (now Executive Engineer (R&B), Kakinada), for failure to monitor/supervise ROB at Rayavaram (V) in lieu of L.C.No.236 at Railway Km.143/10-12 of Guntur-Nandyal Section and R&B Road at K.M.37.2 of Podili-Markapur Road in Prakasam District.

- 2. Against the above said charge, the Charged Officer, submitted, vide reference second read above, his Written Statement of Defence and denied the charge; and, requested to exonerate him.
- 3. On the above said Written Statement of Defence of Charged Officer, Engineer-in-Chief (R&B) Administration, has reported, vide reference fourth read above, that there is a lapse on the part of Assistant Executive Engineer / Deputy Executive Engineer / Executive Engineer in understanding the drawing; and, hence the explanation of the Charged Officer is not convincing.
- 4. Government, after careful examination of the matter, observe that there was confusion/lack of understanding / interpreting in the drawing / designs, culminating in clear professional failure; on the part of Sri T.Abbanna, the then Executive Engineer (R&B), Markapur. Government, therefore, decide and hereby impose a penalty of stoppage of 4 (four) increments, without cumulative effect, against Sri T.Abbanna, the then Executive Engineer (R&B), Markapur, in respect of ROB at Rayavaram (V) in lieu of L.C.No.236 at Railway Km. 143/10-12 of Guntur-Nandyal Section and R&B Road at K.M.37.2 of Podili- Markapur Road in Prakasam District.
- 5. The Engineer-in-Chief (R&B), Administration shall take further necessary action accordingly.

(BY ORDER AND IN THE NAME OF THE GOVERNOR OF ANDHRA PRADESH)

S.P.SINGH PRINCIPAL SECRETARY TO GOVERNMENT

To

Sri T.Abbanna, Executive Engineer (R&B), **through** the Engineer-in-Chief (R&B) Administration & N.H., A.P., Hyderabad.

The Engineer-in-Chief (R&B), Administration & N.H., A.P., Hyderabad.

Copy to:

The Secretary, Andhra Pradesh Vigilance Commission Hyderabad.

The General Administration (V&E) Department, BRK Bhavan, Hyderabad.

The P.S. to Principal Secretary (R&B) TR&B Department. SF/SC.

//FORWARDED BY ORDER//